

SPEC. INFO	C 5 0 2 8 A - M 0 2 5 0 mm 1 : 2.8	3152011 -S001 -0000 -B23
		APR 22. ' 09


(2) Shock Conditions

Tester	Shock Testing Machine by Dropping
Impact Force	686 m/s ²
Duration of Shock	3.5 ms
Directions & Number of Times	1 Time Respectively in Three Dimensional Directions

3-5. Environmental Temperature Range - 20 to + 50

4. Accessories

- (1) Front Lens Cap 1 piece
- (2) Rear Lens Cap 1 piece
- (3) Fixing Screw 6 piece (For Optional Usage)
- (4) Packing Box 1 piece






ASSEMBLED IN VIETNAM

PENTAX

C5028A-M02

50 mm 1:2.8

Name Plate



SPEC. INFO	3152011-S001-0000-B33
	APR. 22, '09
PENTAX	