

WAY-2C INSTALLATION ON PC

1. From the installation disk or downloaded file, double click on *way2c.msi*.
2. Read the license agreement.
3. If you accept the terms in the licence agreement click on the box, otherwise click “Cancel”.
4. Click on “PC Interfaces” and select:
“Entire feature will be installed on local hard drive.”
5. Most first-time users will also want to select “Help Files”, “User’s Manual”, and “Samples” for installation on the local hard drive
6. When your selections are complete click on the “Next” button.
7. Click on “ Install.”
8. When the installation is complete click on “Finish”.
9. From the Desktop click on “WAY-2C Readme” for the latest information

For free trial:

10. From the desktop click on “Evaluate WAY-2C”. You will have approximately 30 days, or until you decide to purchase and register WAY-2C, to test an almost full-featured version.
Do NOT select “Register WAY-2C”; doing so will terminate your evaluation period.
11. For the next 30 days you can start WAY-2C by clicking on the “WAY-2C 3.0” icon on the desktop. An “About” window containing the evaluation period information will appear.

To purchase and register WAY-2C:

12. To purchase a license with USB hardware key to unlock the full power of WAY-2C, contact your vision integrator or:
RMA Electronics, Inc.
35 Pond Park Rd., Unit #12
Hingham, MA 02043
TEL: 781-749-9700
FAX: 781-749-9707
Email: sales@rmaelectronics.com
web: <http://www.rmaelectronics.com>
13. With the hardware key available, but not plugged in to the computer, from the desktop click on “Register WAY-2C”. Fill in the dialog box, then click “OK”.
14. Insert hardware key if prompted. In pre-Vista systems let the ‘Add New Hardware Wizard’ run.
15. From the desktop click on “WAY-2C 3.0”. WAY-2C should start up without any hardware key warning. Click on “Help” and then “About” to verify the information is correct.

Manual installation of Hardware Key

If, for some reason WAY-2C fails to detect the hardware key after registration, you can try to install the key manually. To do this, have the key available but make sure it is not plugged in to the computer. Then:

16. From Windows Explorer go to C:\Program Files\WAY-2C\WAY-2C 3.0\
17. Click on *klkinst.exe* and select USB from the install dialog box.
18. Insert hardware key when prompted.
19. (Pre-Vista systems) Let the ‘Add New Hardware Wizard’ run.
20. If any problems occur, search for and view the log file *kl2log.htm* for details.